Attorney Docket No. 1293.1197

DEC 07 2006 W

HE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent Application of:

Certificate

Byung-in MA et al.

DEC 1 1 2006

Application No.: 09/815,345

ATTENTION

of Correction

Confirmation No.: 4409

CERTIFICATE OF CORRECTION

Filed: March 23, 2001

BRANCH

U.S. Patent No.: 7,120,095

Issued: October 10, 2006

For:

APPARATUS FOR GENERATING SEEK DIRECTION DETECTING SIGNAL USING

TRACK ERROR AND TRACK CROSS SIGNALS FOR AN OPTICAL PICKUP

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents PO Box 1450 Alexandria, VA 22313-1450

Sir:

Patentee(s) respectfully request(s) that a Certificate of Correction be issued in the subject patent, pursuant to 35 U.S.C. §254 and 37 C.F.R. §1.322, to correct the mistake(s) shown on the attached Form PTO-1050.

Since the mistakes are Patent Office mistakes, it is believed that no fee is required.

Respectfully submitted,

STEIN, MCEWEN & BUI, LLP

D - 1 -

SEC. 7 2006

James G. McEw

Registration No. 41,983

1400 Eye St., N.W.

Suite 300

Washington, D.C. 20005 Telephone: (202) 216-9505 Facsimile: (202) 216-9510 Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. (Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO: 7,120,095

DATED: October 10, 2006

INVENTOR(S): Byung-in MA et al.

Column 10, line 33, change "S(p3-p4)" to - - S(p3-p2) --

Column 10, line 63, change "detectin" to --detecting --

Column 10, line 64, change "aignal" to -- signal --

Column 11, lines 15 and 16, change "sub-beam" to -- main beam --

Column 11, line 24, change "signal" to - signals --

Column 13, line 15, change "sub- beam" to -- sub-beam --

Column 13, line 45, start new paragraph after "wherein"

MAILING ADDRESS OF SENDER: STEIN, MCEWEN & BUI, LLP

1400 Eye St., N.W. Suite 300 Washington, DC 20005 PATENT NO. 7,120,095

No. of add'l copies @ 50¢ per page

Ψ